Applicant(s): Longacre, et al.
Filed: August 8, 2003
Customer No. 03000
For: JOINT RESTRAINT ASSEMBLY
Docket No.:S1097/20001
Sheet 1 of 9





Fig. 1

Applicant(s): Longacre, et al.
Filed: August 8, 2003
Customer No. 03000
For: JOINT RESTRAINT ASSEMBLY
Docket No.:S1097/20001



Applicant(s): Longacre, et al.
Filed: August 8, 2003
Customer No. 03000
For: JOINT RESTRAINT ASSEMBLY
Docket No.:S1097/20001
Sheet 3 of 9





Fig. 2

Applicant(s): Longacre, et al. Filed: August 8, 2003 Customer No. 03000

For: JOINT RESTRAINT ASSEMBLY

Docket No.:S1097/20001

Sheet 4 of 9



Applicant(s): Longacre, et al.
Filed: August 8, 2003
Customer No. 03000
For: JOINT RESTRAINT ASSEMBLY
Docket No.:S1097/20001

Sheet 5 of 9 -16 Pipe Wall Thickness

Fig. 4

Applicant(s): Longacre, et al. Filed: August 8, 2003 Customer No. 03000

For: JOINT RESTRAINT ASSEMBLY

Docket No.:S1097/20001 Sheet 6 of 9




Fig. 5

Applicant(s): Longacre, et al. Filed: August 8, 2003 Customer No. 03000

For: JOINT RESTRAINT ASSEMBLY Docket No.:S1097/20001

Sheet 7 of 9




Fig. 6

Applicant(s): Longacre, et al. Filed: August 8, 2003
Customer No. 03000

For: JOINT RESTRAINT ASSEMBLY

Docket No.:S1097/20001 Sheet 8 of 9




Fig. 7

Applicant(s): Longacre, et al. Filed: August 8, 2003 Customer No. 03000 For: JOINT RESTRAINT ASSEMBLY Docket No.:S1097/20001 Sheet 9 of 9




Fig. 7a